

807

TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 214696 _____ WAS TESTED


AND FOUND TO OSCILLATE AT 2540 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO

READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 214848 _____ WAS TESTED


AND FOUND TO OSCILLATE AT 4732 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO

READ 65 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



807

VINELAND AUTO ELECTRIC INC.

Date:

1327

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

04/17/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2004 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 807

20 24

Vehicle Ident No. 119145

30 33

Mileage: 85119

40 42

Tag No. MG57530

50 52

60 61

Signature: *Joseph E. Burt*

70 70