


810

TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 4704 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1094 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



810

TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 13684 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2517 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____


VINELAND AUTO ELECTRIC INC.

Date:

1324

328 South Delsea Drive
Vineland, NJ 08360
(856) 691-5845

04/17/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2004 FORD CROWN VICTORIA

Actual Speed	
--------------	--

Vehicle No : 810

20	20
----	----

Vehicle Ident No. 102521

30	30
----	----

Mileage: 55512

40	40
----	----

Tag No. MG64765

50	50
----	----

60	60
----	----

70	70
----	----

Signature: *Joseph E. Butts*