

811

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 070486 _____ WAS TESTED


AND FOUND TO OSCILLATE AT 1098 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO

READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 070699 _____ WAS TESTED

AND FOUND TO OSCILLATE AT 2513 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO

READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



811

VINELAND AUTO ELECTRIC INC.

Date:

1342

328 South Delsea Drive
Vineland, NJ 08360
(856) 691-5845

04/19/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 811

20 21

Vehicle Ident No. 102520

30 31

Mileage: 42148

40 41

Tag No. MG64764

50 51

60 60

Signature: *[Handwritten Signature]*

70 70