

813

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 209592 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2538 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____
[Signature]

813

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 210550 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 4735 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO
READ 65 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____
[Signature]

VINELAND AUTO ELECTRIC INC.

Date:

1341

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

04/19/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 813

20 22

Vehicle Ident No. 117325

30 32

Mileage: 59241

40 41

50 51

Tag No. MG62254

60 60

70 70

Signature: *Joseph E. Burt*