Ceri	tificate of March 4, 2009	Accuracy	
THIS IS TO CERTIFY THAT ON			
TUNING FORK SERIAL NUMBER AND FOUND TO OSCILLATE AT	2514		WAS TESTED _CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOP 80	PPLER RADAR OPERATII		GHZ BAND TO
READ		МРН.	Mulally I
R & R RADAR, INC. 762 WHITE HORSE PIKE ATCO, N.J. 08004	SIGNED		Williaming

TUNING FORK

Certificate of Accuracy

March 4, 2009 THIS IS TO CERTIFY THAT ON. S1009 **TUNING FORK SERIAL NUMBER** WAS TESTED 1100 AND FOUND TO OSCILLATE AT _ CYCLES PER SECOND. SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE $35\,$ 10.525 GHZ BAND TO READ. R & R RADAR, INC. **762 WHITE HORSE PIKE** SIGNED ATCO, N.J. 08004

©1994 Goes 4418

818

All Rights Reserved

VINELAND AUTO ELECTRIC INC. Date: 328 South Delsea Drive 04/17/2007 1322 Vineland, NJ 08360 (856) 691-5845 **Master Speedometer Service Station Since 1952** Speedometer Tested For: CITY OF VINELAND POLICE DEPT. 2005 FORD CROWN VICTORIA Model: Actual **Speed** Vehicle No: 818 20 22 30 32 Vehicle Ident No. 117319 42 40 Mileage: 76212 50 52 60 62 Lyh & But MG62251 Tag No. 71 Signature: