

821

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 181811 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2515 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____ 

821

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 182170 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1100 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____ 

VINELAND AUTO ELECTRIC INC.

Date:

328 South Delsea Drive
Vineland, NJ 08360
(856) 691-5845

04/17/2007

1320

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 821

20 21

Vehicle Ident No. 117327

30 31

Mileage: 82868

40 40

Tag No. MG62253

50 50

60 60

Signature: *Joseph E. Burt*

70 70