

823

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 070542 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1100 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved


TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 070061 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2513 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

823

All Rights Reserved

VINELAND AUTO ELECTRIC INC.

Date:

1319

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

04/17/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2007 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 823

20 20

Vehicle Ident No. 114381

30 30

Mileage: 15954

40 40

Tag No. MG68998

50 50

Signature: *Joseph E. Butts*

60 60

70 70