

824

# TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON \_\_\_\_\_


TUNING FORK SERIAL NUMBER 070564 \_\_\_\_\_ WAS TESTED

AND FOUND TO OSCILLATE AT 1100 \_\_\_\_\_ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 \_\_\_\_\_ GHZ BAND TO  
READ 35 \_\_\_\_\_ MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_



# TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON \_\_\_\_\_


TUNING FORK SERIAL NUMBER 070651 \_\_\_\_\_ WAS TESTED

AND FOUND TO OSCILLATE AT 2512 \_\_\_\_\_ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 \_\_\_\_\_ GHZ BAND TO  
READ 80 \_\_\_\_\_ MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_



824

825


# TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON \_\_\_\_\_  
181813  
TUNING FORK SERIAL NUMBER \_\_\_\_\_ WAS TESTED  
2516  
AND FOUND TO OSCILLATE AT \_\_\_\_\_ CYCLES PER SECOND.  
10.525  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE \_\_\_\_\_ GHZ BAND TO  
80  
READ \_\_\_\_\_ MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_



©1994 Goes 4418

All Rights Reserved


# TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON \_\_\_\_\_  
180752  
TUNING FORK SERIAL NUMBER \_\_\_\_\_ WAS TESTED  
1102  
AND FOUND TO OSCILLATE AT \_\_\_\_\_ CYCLES PER SECOND.  
10.525  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE \_\_\_\_\_ GHZ BAND TO  
35  
READ \_\_\_\_\_ MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_



©1994 Goes 4418

All Rights Reserved

825