

825


TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
181813
TUNING FORK SERIAL NUMBER _____ WAS TESTED
2516
AND FOUND TO OSCILLATE AT _____ CYCLES PER SECOND.
10.525
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE _____ GHZ BAND TO
80
READ _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved


TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
180752
TUNING FORK SERIAL NUMBER _____ WAS TESTED
1102
AND FOUND TO OSCILLATE AT _____ CYCLES PER SECOND.
10.525
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE _____ GHZ BAND TO
35
READ _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

825