

829

TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 182113 WAS TESTED

AND FOUND TO OSCILLATE AT 1100 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO

READ 35 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 181851 WAS TESTED


AND FOUND TO OSCILLATE AT 2514 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO

READ 80 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



829

VINELAND AUTO ELECTRIC INC.

Date:

328 South Delsea Drive

Vineland NJ 08360

(856) 691-5845

Master Speedometer Service Station Since 1952

1335

04/19/2007

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Vehicle No : 829

Vehicle Ident No. 102525

Mileage: 53972

Tag No. MG64770

Signature: *[Handwritten Signature]*

Actual Speed	
20	20
30	30
40	40
50	50
60	60
70	70