

830


TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 60403 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1099 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved


TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER S802 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2515 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

830

VINELAND AUTO ELECTRIC INC.

Date:

1340

328 South Delsea Drive
Vineland, NJ 08360
(856) 691-5845

04/19/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Actual Speed

Vehicle No : 830

20 22

Vehicle Ident No. 117324

30 32

Mileage: 82021

40 42

Tag No. MG62261

50 52

60 62

Signature: *Joseph E. Burt*

70 72