


831

TUNING FORK
Certificate of Accuracy
March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 073513 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1099 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.


R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____


TUNING FORK
Certificate of Accuracy
March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 969574 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2512 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____


831

VINELAND AUTO ELECTRIC INC.

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

Date:

1329

04/17/2007

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2007 FORD CROWN VICTORIA

Actual
Speed

Vehicle No : 831

20

20

Vehicle Ident No. 114383

30

30

Mileage: 10829

40

40

Tag No. MG73150

50

50

Signature:

60

60

70

70