

880

TUNING FORK Certificate of Accuracy

March 4, 2009


THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 155717 _____ WAS TESTED

AND FOUND TO OSCILLATE AT 2620 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO

READ 25 _____ MPH.



R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____

©1994 Goes 4418

All Rights Reserved

TUNING FORK Certificate of Accuracy

March 4, 2009


THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 255187 _____ WAS TESTED

AND FOUND TO OSCILLATE AT 4173 _____ CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO

READ 40 _____ MPH.



R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____

©1994 Goes 4418

All Rights Reserved

880

VINELAND AUTO ELECTRIC INC.

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

Date:

04/17/2007

1317

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 1999 FORD CROWN VICTORIA

Actual Speed

Vehicle No : T-4

20 21

Vehicle Ident No. 20014

30 31

Mileage: 50950

40 40

Tag No. MG30096

50 50

Signature: *Joseph E. Butts*

60 59

70 69