Tuning Fork		
CERTIFICATE OF ACCURACY		
This is to certify that on 8-36-08 tuning fork Serial No. 966.363		
301		cycles per second. Such
	cillation causes a doppler radar operating in theb	
2 401	nen operated over the temperature of -22°F to +140°F no corre	1063
	2	
	MPH	esmy Willan John
316 E	East Ninth Street / Owensboro, KY 42303 GC-026 MPD-184B Rev. 4/01	Technician
Tuning Fork		
CERTIFICATE OF ACCURACY		
	This is to certify that on $8-31-08$ tuning for was tested and found to oscillate at 2.5	
	oscillation causes a doppler radar operating in the	
	When operated over the temperature of -22°F to +140°F no	
		Same Will- The
3	16 East Ninth Street / Owensboro, KY 42303 GC-026 MPD-184B Rev. 4/01	Technician (6)
		<u> </u>
	Certificate of Calib	ration of the second
	This is to certify that all applicable tests and measurements have been	n made on Model
	a Doppler Traffic Radar, Computer Serial Number	Gr III
	Antenna Serial Number 83/003/75	
	Antenna Serial Number 85500352	8
	Operating Frequency /	Band
	The aforesaid radar meets or exceeds all manufacturer's specification	ns.
	Date 9-18-08 Signed Myony	William Hollier
(316 East Ninth Street Owensboro, KY 42303
	BAPES HE	MPD-201AUS