

GLASSBORO POLICE DEPARTMENT RADAR UNIT INFORMATION FORM

Date 1/15/09

Patrol Unit # 907

Radar Unit Box GPD ID # 00170

Box Unit Serial # 41060

Front Antenna GPD ID # 00172

Front Antenna serial # 41062

Rear Antenna GPD ID # _____

Rear Antenna serial # _____

Tuning Fork serial # 35MPH# 001341

80MPH# 003094

Tuning Fork holder Yes No

Unit condition _____


Officer Name Cpl. Polillo

TUNING FORK
Certificate of Accuracy

THIS IS TO CERTIFY THAT ON FEBRUARY 14, 2008
TUNING FORK SERIAL NUMBER 001341 WAS TESTED
AND FOUND TO OSCILLATE AT 1100 CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.530 GHZ BAND TO
READ 35 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



Certificate of Calibration

THIS IS TO CERTIFY THAT ALL APPLICABLE TESTS AND MEASUREMENTS HAVE BEEN MADE ON


MODEL K-55 BAND X-BAND MFTR MPH IND
SERIAL NUMBER 41060 ANT. #1 41061 ANT. #2 XXXXX

A "DOPPLER" TRAFFIC RADAR. THE AFORESTATED RADAR MEETS AND EXCEEDS ALL SPECIFICATIONS

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

DATE December 23, 2007

SIGNED _____



Certificate of Calibration

THIS IS TO CERTIFY THAT ALL APPLICABLE TESTS AND MEASUREMENTS HAVE BEEN MADE ON

MODEL K-55 BAND X-BAND MFTR MPH IND, INC
SERIAL NUMBER 41060 ANT. #1 41061 ANT. #2 41062

A "DOPPLER" TRAFFIC RADAR. THE AFORESTATED RADAR MEETS AND EXCEEDS ALL SPECIFICATIONS

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

DATE FEBRUARY 14, 2008

SIGNED _____




TUNING FORK
Certificate of Accuracy

March 26, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 003094 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2515 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



All Rights Reserved

©1994 Goes 4418

TUNING FORK
Certificate of Accuracy

March 26, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 001341 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 1101 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



All Rights Reserved

©1994 Goes 4418


TUNING FORK
Certificate of Accuracy

FEBRUARY 14, 2008

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 003094 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2513 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 _____ GHZ BAND TO
READ 80 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



All Rights Reserved

©1994 Goes 4418