



Florence Township Police Department Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0105 Hrs
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	400	MG85206	2009	C / V
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Sgt. Nick Czepiel 	19. Vehicle Operator: Ptl. Jason Silk 
--	---



Florence Township Police Department Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0110 hrs
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # 177049 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # 277769 IFO antenna.
(You should receive a reading of 40 in the target window.)



09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	SOUTH/SOUTH	4049	401	W63EDM	2014	TAHOE
30 MPH	30 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Sgt. Nick Czepiel 	19. Vehicle Operator: Ptl. Jason Silk 
--	---

Florence Township Police Department

Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0113 HRS.					
<p>5. Turn the RADAR on. <input checked="" type="checkbox"/></p> <p>6. Push self test button, unit should read 888/888/188 Pass <u> X </u> Fail <u> </u>. <input checked="" type="checkbox"/></p> <p>7. With Unit in stationary mode struck 25mph fork # <u>FA177085</u> IFO antenna. (You should receive a reading of 25 in the target window.) <input checked="" type="checkbox"/></p> <p>8. Struck 40mph fork # <u>FB277677</u> IFO antenna. (You should receive a reading of 40 in the target window.) <input checked="" type="checkbox"/></p>								
09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	404	MG93730	2012	TAHOE
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	59 MPH	-1	South / South	SAME	SAME	SAME	SAME	SAME
(+) Speedometer reads faster than actual vehicle speed.				(-) Speedometer reads slower than actual vehicle speed.				
18. RADAR Operator: Sgt. Nick Czepiel 				19. Vehicle Operator: Ptl. Jason Silk 				

Florence Township Police Department

Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0121 Hrs
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail _____.
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	407	MG86294	2010	Tahoe
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Sgt. Nick Czepiel <i>Nick Czepiel</i>	19. Vehicle Operator: Ptl. Jason Silk <i>Jason Silk</i>
---	---

Florence Township Police Department



Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0129 Hrs
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail _____.
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	411	MG88866	2011	Tahoe
30 MPH	30 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Sgt. Nick Czepiel 	19. Vehicle Operator: Ptl. Jason Silk 
--	---

Florence Township Police Department



Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0134 Hrs
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail _____
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	411	17791MG	2016	Tahoe
30 MPH	30 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	Same / Same	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Sgt. Nick Czepiel 	19. Vehicle Operator: Ptl. Jason Silk 
--	---

Florence Township Police Department


Stalker Speed Calibration Sheet


Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0138 HRS.
----------------------------	---	----------------------------------	------------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail _____.
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	413	MG91736	2012	TAHOE
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: **Sgt. Nick Czepiel**


19. Vehicle Operator: **Ptl. Jason Silk**


Florence Township Police Department Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Ptl. Jason Silk	3. Radar Unit: DS33106	4. Time: 0141ERS.
----------------------------	---------------------------------------	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # FA167058 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB266751 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4041	419	16943MG	2015	TAHOE
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME

(+ Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: Ptl. Jason Silk 	19. Vehicle Operator: Sgt. Nick Czopiel
--	--

Florence Township Police Department


Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0142HRS.
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # FA177085 IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # FB277677 IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	South / South	4049	416	MG99896	2014	TAHOE
30 MPH	30 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	South / South	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: **Sgt. Nick Czepiel**


19. Vehicle Operator: **Ptl. Jason Silk**




Florence Township Police Department Stalker Speed Calibration Sheet

Date: **12/23/2016** 2. Officer: **Sgt. Nick Czepiel** 3. Radar Unit: **DS34806** 4. Time: **0153 HRS**

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # **FA177085** IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # **FB277677** IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	SOUTH/SOUTH	4049	420	16942MG	2015	TAHOE
30 MPH	30 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: **Sgt. Nick Czepiel**  19. Vehicle Operator: **Ptl. Jason Silk** 

Florence Township Police Department

Stalker Speed Calibration Sheet

Date: 12/23/2016	2. Officer: Sgt. Nick Czepiel	3. Radar Unit: DS34806	4. Time: 0200 HRS
----------------------------	---	----------------------------------	-----------------------------

- 5. Turn the RADAR on.
- 6. Push self test button, unit should read 888/888/188 Pass X Fail .
- 7. With Unit in stationary mode struck 25mph fork # **FA177085** IFO antenna.
(You should receive a reading of 25 in the target window.)
- 8. Struck 40mph fork # **FB277677** IFO antenna.
(You should receive a reading of 40 in the target window.)

09. Vehicle Speed	10. RADAR Speed	11. Difference	12. Direction Vehicle/RADAR	13. Vehicle Driver	14. Vehicle Number	15. Vehicle Registration	16. Vehicle Year	17. Vehicle Type
20 MPH	20 MPH	0	SOUTH/SOUTH	4049	421	16941MG	2015	TAHOE
30 MPH	30 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
40 MPH	40 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
50 MPH	50 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME
60 MPH	60 MPH	0	SAME	SAME	SAME	SAME	SAME	SAME

(+) Speedometer reads faster than actual vehicle speed. (-) Speedometer reads slower than actual vehicle speed.

18. RADAR Operator: **Sgt. Nick Czepiel**



19. Vehicle Operator: **Ptl. Jason Silk**

