



# Commonwealth of Pennsylvania Department of Transportation

## BUREAU OF MOTOR VEHICLES CERTIFICATE OF SPEEDOMETER ACCURACY

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

This is to certify that \_\_\_\_\_  
(NAME OF INDIVIDUAL OR COMPANY)

has been designated as official Speedometer Testing Station No. S-19 by the SECRETARY OF TRANSPORTATION.

On May 7, 2009 the speedometer of FORD SW  
(DATE) (MAKE OF VEHICLE - MODEL)  
bearing Manufacturer's No. 1FMPV15535LA90324 and Registration No. MG66482 was

( X ) tested for accuracy, ( ) adjusted for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR									
	10	20	30	40	50	60	70	80	90	100
SPEED INDICATED BY SPEEDOMETER	10	20	30	40	51	62	73	84	-	-

This Certificate is issued in accordance with the provisions of the Vehicle Code, Section 3368(b) Act of June 17, 1976, No. 81, as amended.

### TEST EQUIP.

Make MUSTANG DYNO.

Model MD-66

Ser. No. 18705

### POLICE EQUIP.

No. 3001  
(IF APPLICABLE)

[Signature]  
(INSPECTOR'S NAME)  
**DANIEL G. BREY**  
(PRINT NAME AS IT APPEARS ABOVE)

26862809  
(INSPECTOR'S OPERATOR NUMBER)

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.  
(STATION NAME)

181 RIDGE ROAD, TELFORD, PA 18969  
(STATION ADDRESS)



# Certificate of



# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Sept. 26, 2008 the speedometer of Ford SW  
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 1FMPU15535LA 90324

Registration No. ML 66482

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	42	52	62	73	83

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

Cory Eef  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 3001  
(IF APPLICABLE)