

819

TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 212256 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2538 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO
READ 35 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

TUNING FORK
Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 214819 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 4732 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 24.150 _____ GHZ BAND TO
READ 65 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

819