

826

TUNING FORK

Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 60404 WAS TESTED

AND FOUND TO OSCILLATE AT 1097 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO

READ 35 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



TUNING FORK

Certificate of Accuracy

March 4, 2009

THIS IS TO CERTIFY THAT ON _____

TUNING FORK SERIAL NUMBER 70418 WAS TESTED


AND FOUND TO OSCILLATE AT 2510 CYCLES PER SECOND.

SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO

READ 80 MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



826

VINELAND AUTO ELECTRIC INC.

328 South Delsea Drive
Vineland NJ 08360
(856) 691-5845

Date:

04/17/2007

1321

Master Speedometer Service Station Since 1952

Speedometer Tested For: CITY OF VINELAND POLICE DEPT.

Model: 2005 FORD CROWN VICTORIA

Actual Speed	
--------------	--

Vehicle No : 826

20	20
----	----

Vehicle Ident No. 102523

30	30
----	----

Mileage: 54776

40	40
----	----

Tag No. MG64767

50	50
----	----

60	60
----	----

Signature: 

70	70
----	----