


TUNING FORK
Certificate of Accuracy

April 27, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 264409 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 4164 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 40 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

TUNING FORK
Certificate of Accuracy

April 27, 2009

THIS IS TO CERTIFY THAT ON _____
TUNING FORK SERIAL NUMBER 165189 _____ WAS TESTED
AND FOUND TO OSCILLATE AT 2614 _____ CYCLES PER SECOND.
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 34.700 _____ GHZ BAND TO
READ 25 _____ MPH.

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

SIGNED _____



©1994 Goes 4418

All Rights Reserved

Certificate of Calibration

THIS IS TO CERTIFY THAT ALL APPLICABLE TESTS AND MEASUREMENTS HAVE BEEN MADE ON
MODEL STALKER DSR BAND KA - BAND MFR APPLIED CONCEPTS, INC
SERIAL NUMBER 32777 ANT. #1 025333 ANT. #2 025354

A "DOPPLER" TRAFFIC RADAR THE AFORESTATED RADAR MEETS AND EXCEEDS ALL SPECIFICATIONS

R & R RADAR, INC.
762 WHITE HORSE PIKE
ATCO, N.J. 08004

DATE April 27, 2009
SIGNED _____



© GOES 406

LITHO IN U.S.A.