



Certificate



207

of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 1FMFU15539EB20086

Registration No. MG83974

was tested for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR							
	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	23	33	43	53	63	73	83

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 1
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 15 2011 the speedometer of Ford SC
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 1FMAFU16S28LA63288

Registration No. MG5070

was tested for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR							
	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	27	33	43	53	64	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 2
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) . MODEL)

Manufacturer's No. FMPUIS556LA60534

Registration No. MG80291

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	33	43	54	64	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 5
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 1FMFU15539EB20086

Registration No. MG83974

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	23	33	43	53	63	73	83

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 1
(IF APPLICABLE)



Certificate of



Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 1FMPU16528LA63288

Registration No. MG8070

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	33	43	53	64	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 2
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) MODEL

Manufacturer's No. FMPULSS56LA60534

Registration No. MG80791

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	33	43	54	64	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. S
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) MODEL


Manufacturer's No. 2FAFP71V18X120831

Registration No. MG-75785

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	42	52	62	72	82

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 4
(IF APPLICABLE)



Certificate



207

of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of FORD SIV
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FAFP71V38X120838

Registration No. MG 75784

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	41	51	62	72	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 7
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 1FMEU70E7AUA78676

Registration No. MG87633

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	33	43	54	64	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 8
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
 has been designated as official Speedometer Testing Station No. S-19 by the
 SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
 DEPARTMENT OF TRANSPORTATION.

On May 25 2011 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) - MODEL


Manufacturer's No. 2FAA71VSBX122839

Registration No. MG 757 86

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	61	71	81

TEST EQUIPMENT
 MAKE CLAYTON
 MODEL C700 SECE
 SER. NO. 10670-R


 CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 10
(IF APPLICABLE)



Certificate



207

of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford S.D.W
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FABP7BV6BX109266

Registration No. MG88849

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	40	50	60	71	81

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. cf
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SDW
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAHP21V99X144717

Registration No. MG83977

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	40	51	61	71	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 11
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford S.D.W
(DATE) (MAKE OF VEHICLE) MODEL


Manufacturer's No. 2FAP71W80X165506

Registration No. MG70864

was tested for accuracy, and the degree of accuracy was as follows:

MILES PER HOUR								
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	61	71	82

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 12
(APPLICABLE)



Certificate



207

of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SDN
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FAFP71V48X155209

Registration No. MG-54909

was tested for accuracy, and the degree of accuracy was as follows:

MILES PER HOUR								
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	32	42	52	62	72	83

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 13
(IF APPLICABLE)



Certificate



207

of

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SUV
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FAFP71V98X175620

Registration No. MG 80779

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	52	62	72	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 14
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford S.DW
(DATE) (MAKE OF VEHICLE) MODEL

Manufacturer's No. 2FAHP71V09X144718

Registration No. MG83973

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	32	42	52	62	72	82

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 15
(IF APPLICABLE)



Certificate of



Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford Focus
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAFP71W16X165508

Registration No. MC-70863

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	41	57	61	71	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO.

18
(IF APPLICABLE)



Certificate of



Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 (DATE) the speedometer of Ford Focus (MAKE OF VEHICLE) - Focus (MODEL)


Manufacturer's No. 2FAFP71V19X120840

Registration No. MG 75287

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	41	51	61	71	82

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 19
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On May 05 2011 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) - MODEL


Manufacturer's No. 2FAMPT71V29X144719

Registration No. YLT-81P

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	31	41	51	62	72	82

TEST EQUIPMENT
MAKE CLAYTON
MODEL C700 SECE
SER. NO. 10670-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. Situra
(IF APPLICABLE)