



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Chrysler
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 1GN1C2E05DR123908

Registration No. MG93743

was tested for accuracy, and the degree of accuracy was as follows:

| MILES PER HOUR | | | | | | | | |
|--------------------------------|----|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 10 | 20 | 30 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO.
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.
has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE) MODEL

Manufacturer's No. 1FMRU165281A63228

Registration No. MG80790

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 12 | 22 | 33 | 43 | 53 | 63 | 73 | 83 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 2
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On JUNE 27 2013 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FAFP71V28X155211

Registration No. MG 90582

was tested for accuracy, and the degree of accuracy was as follows:

| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |

TEST EQUIPMENT
MAKE CLAYTON
MODEL PSN
SER. NO. C-1474-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 3
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford Focus
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FA7P7BVL6BX108266

Registration No. MG 888 49

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT
MAKE CLAYTON
MODEL PSN
SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 4
(IF APPLICABLE)



207

Commonwealth of Pennsylvania Department of Transportation

BUREAU OF MOTOR VEHICLES

CERTIFICATE OF SPEEDOMETER ACCURACY

This is to certify that DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(NAME OF INDIVIDUAL OR COMPANY)

has been designated as official Speedometer Testing Station No. S-19 by the SECRETARY OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE - MODEL)

bearing Manufacturer's No. 1FMSK8ARXDGA63921 and Registration No. MG93739 was

(X) tested for accuracy, () adjusted for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED SPEED INDICATED BY SPEEDOMETER | MILES PER HOUR | | | | | | | | | |
|---|----------------|----|----|----|----|----|----|----|----|-----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 | 90 | 100 |
| | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 | 91 | 101 |

This Certificate is issued in accordance with the provisions of the Vehicle Code, Section 3368(b) Act of June 17, 1976, No. 81, as amended.

TEST EQUIP.

Make STORAGE GENERATOR

Model SPEEDOMETER CALIBRATOR

Ser. No. D101

POLICE EQUIP.

No. 5
(IF APPLICABLE)

BARRY L. ROSENBERGER

(PRINT NAME AS IT APPEARS ABOVE)

16789324

(INSPECTOR'S OPERATOR NUMBER)

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD, TELFORD, PA 18969

(STATION ADDRESS)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Chevy SW
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 16N1C2E00BR281067

Registration No. 1M69170J

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT
MAKE CLAYTON
MODEL PSN
SER. NO. C-1474-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 6
(IF APPLICABLE)



Certificate of



201

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On JUN 27 2013 the speedometer of Ford Focus
(DATE) (MAKE OF VEHICLE) MODEL

Manufacturer's No. 2FAFP21V38X120838

Registration No. MG 75784

was tested for accuracy, and the degree of accuracy was as follows:

| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 7
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On Dec 27 2013 the speedometer of Ford SUV
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 1FMEU70E7AUA78676

Registration No. MG87633

was tested for accuracy, and the degree of accuracy was as follows:


| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 12 | 22 | 32 | 42 | 52 | 63 | 73 | 83 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 8
(IF APPLICABLE)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Chevy SW
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 1GALC2E05DR124119

Registration No. KND-97V

was tested for accuracy, and the degree of accuracy was as follows:

| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R

[Signature]
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 9
(IF APPLICABLE)



207

Commonwealth of Pennsylvania Department of Transportation

BUREAU OF MOTOR VEHICLES CERTIFICATE OF SPEEDOMETER ACCURACY

This is to certify that DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(NAME OF INDIVIDUAL OR COMPANY)

has been designated as official Speedometer Testing Station No. S-19 by the SECRETARY OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SW
(DATE) (MAKE OF VEHICLE - MODEL)

bearing Manufacturer's No. 1FASK8ARSD6A63910 and Registration No. MG-93738 was

(X) tested for accuracy, () adjusted for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED SPEED INDICATED BY SPEEDOMETER | MILES PER HOUR | | | | | | | | | |
|---|----------------|----|----|----|----|----|----|----|----|-----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 | 90 | 100 |
| | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 | 91 | 101 |

This Certificate is issued in accordance with the provisions of the Vehicle Code, Section 3368(b) Act of June 17, 1976, No. 81, as amended.

TEST EQUIP.

Make STORAGE GENERATOR

Model SPEEDOMETER CALIBRATOR

Ser. No. D101

POLICE EQUIP.

No. 10
(IF APPLICABLE)

BARRY L. ROSENBERGER

(PRINT NAME AS IT APPEARS ABOVE)

16789324

(INSPECTOR'S OPERATOR NUMBER)

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD, TELFORD, PA 18969

(STATION ADDRESS)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On JUNE 27 2013 the speedometer of Ford SDW
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2F0HP71V9X144717

Registration No. MG83972

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT
MAKE CLAYTON
MODEL PSN
SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 11
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford Focus
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2F0BP7B19BX112585

Registration No. MG90597

was tested for accuracy, and the degree of accuracy was as follows:

| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 12
(IF APPLICABLE)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FAFP71V48X85209

Registration No. MG54909

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 32 | 42 | 52 | 62 | 72 | 82 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 13
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SUV
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FAFP71V98X170620

Registration No. MG 80779

was tested for accuracy, and the degree of accuracy was as follows:

| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT
MAKE CLAYTON
MODEL PSN
SER. NO. C-1474-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.
(STATION NAME)
181 RIDGE ROAD TELFORD, PA 18969
(STATION ADDRESS)

EQUIP. NO. 14
(IF APPLICABLE)



Certificate



of

Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SDW
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2F0AP71V09X144708

Registration No. MG83973

was tested for accuracy, and the degree of accuracy was as follows:


| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 15
(IF APPLICABLE)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SDN
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAHP71V29X144719

Registration No. 1LT81P

was tested for accuracy, and the degree of accuracy was as follows:


| TRUE SPEED | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 10 | 20 | 30 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 16
(IF APPLICABLE)



Certificate of



207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA.

DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Pontiac Solar
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAFP71V18X120837

Registration No. MG 75785

was tested for accuracy, and the degree of accuracy was as follows:

| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R


CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 19
(IF APPLICABLE)



Certificate



of

207

Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,
DEPARTMENT OF TRANSPORTATION.

On June 27 2013 the speedometer of Ford SON
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FABP7BVX3X106298

Registration No. MG 90596

was tested for accuracy, and the degree of accuracy was as follows:


| | MILES PER HOUR | | | | | | | |
|--------------------------------|----------------|----|----|----|----|----|----|----|
| TRUE SPEED | 10 | 20 | 30 | 40 | 50 | 60 | 70 | 80 |
| SPEED INDICATED BY SPEEDOMETER | 11 | 21 | 31 | 41 | 51 | 61 | 71 | 81 |

TEST EQUIPMENT

MAKE CLAYTON

MODEL PSN

SER. NO. C-1474-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 18
(IF APPLICABLE)