



# Certificate of



*2011*

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SC  
(DATE) (MAKE OF VEHICLE) - MODEL


Manufacturer's No. 1FMEU15539EB20086

Registration No. MG83974

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	32	42	53	63	73	83

TEST EQUIPMENT  
MAKE CLAYTON  
MODEL C700 SECE  
SER. NO. 10670-R

  
\_\_\_\_\_  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.  
(STATION NAME)  
181 RIDGE ROAD TELFORD, PA 18969  
(STATION ADDRESS)

EQUIP. NO. 1  
(IF APPLICABLE)



# Certificate of



207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SC  
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 1FMFU16528LA6329E

Registration No. MG80790

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	33	43	53	63	74	84

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 2  
(IF APPLICABLE)



# Certificate



# of

# Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On OCT 20 2011 the speedometer of Ford SDN  
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FAFP71V28X155211

Registration No. MG 90582

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	61	72	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R



CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 3  
(IF APPLICABLE)



# Certificate of



207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SDW  
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FABP7BVG0BX109266

Registration No. MC-88849

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	31	41	51	61	72	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 4  
(IF APPLICABLE)



# Certificate



207

# of

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On OCT 20 2011 the speedometer of Ford SVT  
(DATE) (MAKE OF VEHICLE) - (MODEL)

Manufacturer's No. FMPUIS56A00534

Registration No. MG-80791

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	32	42	53	63	73	83

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. ←  
(IF APPLICABLE)



# Certificate of



207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On 01 20 2011 the speedometer of FORD SON  
(DATE) (MAKE OF VEHICLE) - MODEL)

Manufacturer's No. 2FAFP71V18X120837

Registration No. MG 75785

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	40	50	61	71	81

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 6  
(IF APPLICABLE)



# Certificate of



207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 24 2011 the speedometer of Ford Focus  
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAFP71V39X120838

Registration No. MG-75784

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	61	71	81

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

\_\_\_\_\_  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 7  
(IF APPLICABLE)



# Certificate of



207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SW  
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 1FMEU7DE7AUA78676

Registration No. AG87633

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	52	62	72	83

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

  
CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 8  
(IF APPLICABLE)





# Certificate



# of

# Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford Focus  
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAFP71V4HX155209

Registration No. MC54909

was tested for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR							
	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	12	22	32	42	52	62	72	82

TEST EQUIPMENT  
MAKE CLAYTON  
MODEL C700 SECE  
SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.  
(STATION NAME)  
181 RIDGE ROAD TELFORD, PA 18969  
(STATION ADDRESS)

EQUIP. NO. 13  
(IF APPLICABLE)



# Certificate



## of

# Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SON  
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FAFP71V98X175620

Registration No. MG80719

was tested for accuracy, and the degree of accuracy was as follows:


	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	61	71	81

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

  
 \_\_\_\_\_  
 CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 101  
(IF APPLICABLE)



# Certificate



of

207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford SUV  
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FA1P71V09X144718

Registration No. MG83973

was tested for accuracy, and the degree of accuracy was as follows:

	MILES PER HOUR							
TRUE SPEED	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	10	20	30	40	50	60	71	81

TEST EQUIPMENT  
MAKE CLAYTON  
MODEL C700 SECE  
SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.  
(STATION NAME)  
181 RIDGE ROAD TELFORD, PA 18969  
(STATION ADDRESS)

EQUIP. NO. 15  
(IF APPLICABLE)



# Certificate



## of

207

# Speedometer Accuracy

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On Oct 20 2011 the speedometer of Ford S Dr  
(DATE) (MAKE OF VEHICLE) (MODEL)

Manufacturer's No. 2FAHP71V29X144719

Registration No. VLT-81P

was tested for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR							
	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	62	72	82

TEST EQUIPMENT

MAKE CLAYTON

MODEL C700 SECE

SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.

(STATION NAME)

181 RIDGE ROAD TELFORD, PA 18969

(STATION ADDRESS)

EQUIP. NO. 16  
(APPLICABLE)



# Certificate



## of

# Speedometer Accuracy

207

This is to certify that Davidheiser's Speedometer Repair, Inc.

has been designated as official Speedometer Testing Station No. S-19 by the  
SECRETARY OF TRANSPORTATION, COMMONWEALTH OF PENNSYLVANIA,  
DEPARTMENT OF TRANSPORTATION.

On 02/20/11 the speedometer of FORD SEDAN  
(DATE) (MAKE OF VEHICLE) - MODEL

Manufacturer's No. 2FAFP71V18X120840

Registration No. MG 75787

was tested for accuracy, and the degree of accuracy was as follows:

TRUE SPEED	MILES PER HOUR							
	10	20	30	40	50	60	70	80
SPEED INDICATED BY SPEEDOMETER	11	21	31	41	51	62	72	82

TEST EQUIPMENT  
MAKE CLAYTON  
MODEL C700 SECE  
SER. NO. 10670-R

CALIBRATION TECHNICIAN

DAVIDHEISER'S SPEEDOMETER REPAIR, INC.  
(STATION NAME)  
181 RIDGE ROAD TELFORD, PA 18969  
(STATION ADDRESS)

EQUIP. NO. SR 2  
(IF APPLICABLE)