

## Tuning Fork CERTIFICATE OF ACCURACY

This is to certify that on 5-26-05 tuning fork Serial No. 419275  
was tested and found to oscillate at 1100 cycles per second. Such  
oscillation causes a doppler radar operating in the X band to read 35 mph.  
When operated over the temperature of -22°F to +140°F no correction is required.

**MPH**

316 East Ninth Street / Owensboro, KY 42303

GC-026 MPD-184B Rev. 4/01

*Gregory William Pelt*  
Technician

## TUNING FORK Certificate of Accuracy

THIS IS TO CERTIFY THAT ON May 5, 2010  
TUNING FORK SERIAL NUMBER 419275 WAS TESTED  
AND FOUND TO OSCILLATE AT 1100 CYCLES PER SECOND.  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO  
READ 35 MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_

*[Signature]*

**Tuning Fork  
CERTIFICATE OF ACCURACY**

This is to certify that on 5-26-05 tuning fork Serial No. 413954  
was tested and found to oscillate at 2510 cycles per second. Such  
oscillation causes a doppler radar operating in the X band to read 80 mph.  
When operated over the temperature of -22°F to +140°F no correction is required.

**MPH**

316 East Ninth Street / Owensboro, KY 42303

GC-026 MPD-184B Rev. 4/01

*Suzanne Wilkin*  
Technician

**TUNING FORK  
Certificate of Accuracy**

THIS IS TO CERTIFY THAT ON May 5, 2010  
TUNING FORK SERIAL NUMBER 413954 WAS TESTED  
AND FOUND TO OSCILLATE AT 2510 CYCLES PER SECOND.  
SUCH OSCILLATION CAUSES A DOPPLER RADAR OPERATING IN THE 10.525 GHZ BAND TO  
READ 80 MPH.

**R & R RADAR, INC.**  
762 WHITE HORSE PIKE  
ATCO, N.J. 08004

SIGNED \_\_\_\_\_

*[Signature]*