

STATE OF NEW JERSEY
DEPARTMENT OF LAW AND PUBLIC SAFETY
DIVISION OF STATE POLICE
BREATH TESTING INSTRUMENTATION SERVICE REPORT

1. Department: Longport Borough Police Department 2305 Atlantic Ave Longport, NJ 08403		2. Contact: Dean Tibbit	4. Date: 10/08/2026
		3. Phone Number: 609-822-2141	5. County: Atlantic
6. Alcotest Instrument Serial Number: ARMJ-0201	7. Simulator Component Serial Number: N/A	8. Temperature Probe Component Serial Number: N/A	

9. Reason for Service:

The Alcotest instrument was returned from outside evaluation and placed back in service.

10. Comments:

See Draeger Return and Repair form.

Last Known Sequential File #: N/A

☐ 11. The above Instrument/Component has been found to be in satisfactory working condition; no further action required.

☐ 12. The above Instrument/Component is placed out of service pending further evaluation.

☒ 13. The above Instrument/Component is placed back in service.

"I have been certified by the Attorney General as a Breath Test Coordinator/Instructor pursuant to N.J.A.C. 13:51, et. seq. In my official capacity as a Breath Test Coordinator/Instructor I perform inspections of evidential breath test devices and related components of evidential breath test systems. I have inspected the evidential breath test device listed on this report in my official capacity. The results of my inspection are recorded on this form. I certify that the forgoing statements made by me are true and accurate to the best of my knowledge. I am aware that if any of the forgoing statements made by me are willingly false, I am subject to punishment."

Tpr. II David Bellay #8112

Name & Badge Number (Print)


Signature

10/08/2026

Date

RETURN AND REPAIR FORM

Dräger

Customer Information

B:

S:

Company Name: BOROUGH OF LONGPORT POLICE

Date Received: 10.07.2026

Date given to service: 9.24.26

Carrier: ☐ FedEx ☐ UPS ☐ USPS Shipping Method: ☐ GRD ☐ 3DAY ☐ 2DAY
☐ NDA-PRI ☐ NDA-STD

Product: ☐ 6510 ☐ 6810
☐ 7110 ☐ 8610
☐ 7510 ☐ DT5000
☐ 7410 Upper-half ☒ 9510
☐ 7410 Whole

Serial Number: AR MJ-0201

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: _____

Description: ☐ A ☐ B ☐ Plus ☐ Demo ☐ Screener ☐ Trade In

Accessories

☐ 110V A/C Adapter ☐ Regulator ☐ Printer Ribbon ☐ Printer Paper
☐ Mouthpieces ☐ 9510 Stylus ☒ 9510 Top Cover ☐ Carrying Case
☐ Dry Gas ☐ Other (please specify) _____

Repair Information

Test#:

Part Number	Description	Qty	Total Cost
4414166	Labor	1 HR	
6808455	EC Sensor	1 EA	

Repair Notes: Replaced EC sensor due to Int-T and EC value out of tolerance.

EC SENSOR = ARWF-0111

CAL W/QC AND OPS CHECK

Service Technician IG

Date: 09.24.26

Service Report

Customer No. 0150062710	Contract 317024958	Dispatch No.: U08125648	Date 09/24/2026
Responsible Service Engineer Izak Garcia (5479)			

Postal Address
BOROUGH OF LONGPORT POLICE

Page 1 / 1

2305 ATLANTIC AVE
LONGPORT, NJ08403-1196
NicholasMimikos

Sold To Party
0150062710
BOROUGH OF LONGPORT POLICE

2305 ATLANTIC AVE
LONGPORT, NJ08403-1196

Your order dated
07/13/2026
XC CONTRACT

Your contact person
Nicholas Mimikos
609-571-2855
609-571-2855

Pos.	Quant.	Part No.	Description	EQ. No. / UDI
		8327998	Alcotest 9510 New Jersey Serial No.: ARMJ-0201 S/O 156231961 Return Authorization: 312513141 Inv.No.: Location: Work performed: SENSOR REPLACED AND CALIBRATED	1028389791 /
010	1.00 items	6808455	Sensor Alcotest B	
020	1.00 Hour	R004	Repair Time - Workshop	

Delivery receipt



Customer no.
150062710

Number of report
312513141
Please reference on inquiries

Date of receiving Delivery receipt date
10.07.2026 24.09.2026

Consignee, 150062710
BOROUGH OF LONGPORT POLICE
2305 ATLANTIC AVE
LONGPORT NJ 08403-1196
USA

Customer, 150062710
BOROUGH OF LONGPORT POLICE
2305 ATLANTIC AVE
LONGPORT NJ 08403-1196
USA

Your order

Date of order:
02.07.2026
Purch.ord.no.:
XC CONTRACT

Branch text

Draeger contact person

CONTRACT OPERATIONS
1-800-437-2437
Contract.operations@draeger.com

Page 1

Quantity	Description	Part no.	Equipment - No.	Serial - No.
000	Alcotest 9510 New Jersey	8327998	1028389791	ARMJ-0201
	REPAIR ALCOTEST 9510 10 YR EXT WARR			

Draeger Inc.
Our Tax ID: 23-1699096
3135 Quarry Road; Telford, PA 18969
An Equal Opportunity Employer M / F / V / H
Telephone 800-437-2437
<http://www.draeger.com>

Remit to:
LOCKBOX (Standard USPS)
Draeger, Inc.
PO Box 13369
Newark, New Jersey
07101-3362

Remit to:
LOCKBOX (Overnight)
FIS - Lockbox Operations
Attn:Draeger, Inc., Lockbox #13369
101 Woodcrest Road
Suite 201
Cherry Hill, New Jersey 08003

Remit US Wire Transfers to:
Account Name: Draeger Inc.
Account Number: 00-494-936
Transit Routing: 021001033
SWIFT: BKTRUS33
Deutsche Bank Trust Company Americas
60 Wall Street 25th Fl, New York, NY 10005

Service note

Customer no. Number of report Date of receiving
150062710 312513141 10.07.2026
Please reference on inquiries

Customer
BOROUGH OF LONGPORT POLICE
2305 ATLANTIC AVE
LONGPORT NJ 08403-1196
USA

Consignee
BOROUGH OF LONGPORT POLICE
2305 ATLANTIC AVE
LONGPORT NJ 08403-1196
USA

Your order

Date of order:
02.07.2026
Your reference:
XC CONTRACT

NL-Text

Your contact person

CONTRACT OPERATIONS
1-800-437-2437
Contract.operations@draeger.com

Page 1

Item	Quantity	Part no. Description
		Service Order: 156231961
		REPAIR ALCOTEST 9510 10 YR EXT WARR
		Eq.No. : 1028389791 SN: ARMJ-0201
		Material: 8327998 Alcotest 9510 New Jersey
		Inv.No. :
		Location:
		REPAIR ALCOTEST 9510 10 YR EXT WARR
		 REPAIR ALCOTEST 9510 10 YR EXT WARR
	0,0 H	

STATE OF NEW JERSEY
DEPARTMENT OF LAW AND PUBLIC SAFETY
DIVISION OF STATE POLICE
BREATH TESTING INSTRUMENTATION SERVICE REPORT

1. Department: Longport Borough Police Department 2305 Atlantic Ave Longport, NJ 08403		2. Contact: Dean Tibbitt	4. Date: 06/30/2026
		3. Phone Number: 609-822-2141	5. County: Atlantic
6. Alcotest Instrument Serial Number: ARMJ-0201	7. Simulator Component Serial Number: N/A	8. Temperature Probe Component Serial Number: N/A	

9. Reason for Service:

I responded to the Longport Borough Police Department to perform the semi-annual certification of Alcotest 9510 (Serial number ARMJ-0201).

10. Comments:

On June 30, 2026, I responded to the Longport Borough Police Department to perform a certification of Alcotest 9510 (Serial number ARMJ-0201). On the Linearity (Part III), an "EXTERNAL STANDARD FAILED" error code occurred due to low EC. A check of the performance history revealed several breath tests resulting in "EXTERNAL STANDARD FAILED" error codes due to low EC.

The instrument was placed out of service at this time and returned to Draeger Inc. for evaluation.

Last Known Sequential File #: 00070

☐ 11. The above Instrument/Component has been found to be in satisfactory working condition; no further action required.

☒ 12. The above Instrument/Component is placed out of service pending further evaluation.

☐ 13. The above Instrument/Component is placed back in service.

"I have been certified by the Attorney General as a Breath Test Coordinator/Instructor pursuant to N.J.A.C. 13:51, et. seq. In my official capacity as a Breath Test Coordinator/Instructor I perform inspections of evidential breath test devices and related components of evidential breath test systems. I have inspected the evidential breath test device listed on this report in my official capacity. The results of my inspection are recorded on this form. I certify that the forgoing statements made by me are true and accurate to the best of my knowledge. I am aware that if any of the forgoing statements made by me are willingly false, I am subject to punishment."

Tpr. II David M. Bellay #8112
Name & Badge Number (Print)

Tpr. II David M. Bellay #8112
Signature

06/30/2026
Date